

FIG 1




FIG. 2




FIG. 3




FIG. 4





FIG. 5



#### Six Measurements Obtained

Fa(high)	High
Fa (low)	Low
Fb(high)	
Fb(low)	

FIG 6

$$F_{\text{high}} = F_{\text{a(high)}}/F_{\text{b(high)}}$$

$$F_{\text{low}} = F_{\text{a(low)}}/F_{\text{b(low)}}$$

$$t^* = [\ln (F_{\text{high}}) - \ln (F_{\text{low}})]/(F_{\text{high}} - F_{\text{low}})$$

FIG 7

MAP OF FRACTURED ZONE






FIG 8






FIG. !!